



singing rock®

GRIPPY

Návod k použití, údržbě a skladování rukavic GRIPPY (EN 420, EN 388)

Tyto rukavice jsou určeny k ochraně proti jednoduchým mechanickým rizikům způsobeným oděrem, proříznutím, roztržením a propíchnutím.

Úrovně provedení pro jednotlivá rizika:



2144

TEST	hodnocení úrovně výkonnosti					
	0	1	2	3	4	5
A. Odolnost proti oděru (cykly)	< 100	100	500	2000	800	
B. Odolnost vůči proříznutí (koeficient)	< 1,2	1,2	2,5	5,0	10,0	20
C. Odolnost proti protřetí (newton)	< 10	10	25	50	75	
D. Odolnost vůči propíchnutí (newton)	< 20	20	60	100	150	

Údržba a skladování

Rukavice nevyžadují žádnou zvláštní údržbu. Je možné je očistit hadrem navlhčeným v jemné mýdlové vodě. Nebělit chlorem. Sušit pomalu a volně – nesušit na přímotopích a jiných topných tělesech. Rukavice skladovat v běžných pokojových podmínkách (teplota do 20 °C, relativní vlhkost vzduchu 65%), v suchém a čistém prostředí, minimálně 1 m od topných těles, bez přímého vlivu slunečního záření a z dosahu škůdců.

Upozornění: černé rukavice mohou při navlhčení pouštět barvu.

Dostupný rozsah velikostí: 08; 09; 10; 11



CZ Bez důkladného pročtení a pochopení návodu k použití nepoužívejte tento výrobek.
EN Reading and understanding instruction for use are required to use this product.



CZ 2 roky záruka.
EN 2 years guarantee.

GRIPPY

Instructions for use, maintenance and storage the gloves GRIPPY (EN 420, EN 388)

These gloves are designed to protect against the simple mechanical risks caused by abrasion, cutting, tearing and perforation.

Levels of performance for each risk:



2144

TEST	evaluation of performance level					
	0	1	2	3	4	5
A. Endurance against abrasion (cycles)	< 100	100	500	2000	800	
B. Endurance against cutting (coefficient)	< 1.2	1.2	2.5	5.0	10.0	20
C. Endurance against tearing (newton)	< 10	10	25	50	75	
D. Endurance against puncture (newton)	< 20	20	60	100	150	

Maintenance and Storage

Gloves do not require any special maintenance. They can be cleaned with a cloth dampened with mild soapy water. Do not bleach with chlorine. Dry slowly and freely – do not dry on heaters and other heating elements. Gloves should be stored under normal room conditions (temperature to 20 °C, relative humidity 65%), in dry and clean environment, at least 1 m from heat sources, away from direct solar radiation and away from pests.

Warning: black gloves when wet may release the colour.

Available size range: 08, 09, 10, 11

ver. 16K002202600 0318

SINGING ROCK s.r.o.

Poniklá 317 • 514 01 Poniklá • Czech republic

Tel. +420 481 585 007 • email: info@singingrock.cz

www.singingrock.com



[singingrock.page](https://www.facebook.com/singingrock.page)



[singingrock_official](https://www.instagram.com/singingrock_official)