

# PREVENTIVE RECALL NOTICE

Singing Rock is notifying customers that some of the produced climbing harnesses CRUX, NARA, NEMO may pose a potential casualty hazard due to inaccuracy in the production. This defect was identified at regular internal quality inspection and up to know there are no reports of this defect coming from normal use.

If you own any of mentioned products, please, read this important notice.

## Identification - Name of Product/production lots involved:

The lot number can be found on the label as pictured below and is either the 7 digits in the larger lot number. Compare these 7 digits with the list of numbers given below. In the case of a match, return the product to your dealer as directed below.



---/XXXXXX-/--/--  
**CRUX**  
SIZE: --

---/XXXXXX-/--/--  
**NARA**  
SIZE: --

---/XXXXXX-/--/--  
**NEMO**  
SIZE: --

### CRUX

1071050; 1071051; 1071130; 1075163; 1075162; 1077978;  
1077980; 1062912; 1064334; 1063634; 1071048; 1071049;  
1071129; 1075159; 1075160; 1075161; 1080987; 1071046;  
1071047; 1071128; 1075158; 1077981; 1086111; 1071054;  
1071131; 1077976; 1077977; 1070798; 1071045; 1071127;  
1086110

### NARA

1071104; 1071105; 1071106; 1075178; 1078062; 1062913;  
1063636; 1064362; 1071101; 1071102; 1071103; 1075176;  
1075177; 1078063; 1089901; 1086397; 1071093; 1071100;  
1075174; 1075175; 1071088; 1071090; 1075173; 1085477;  
1085479


### NEMO

1071120; 1071121; 1071122; 1075166; 1075167; 1075168;  
1089748; 1075169; 1062916; 1064364; 1063638; 1071123;  
1071124; 1075170; 1071125; 1075171; 1075172; 1080254;  
1086109

**Manufacturer:** LANEX a.s., division Singing Rock

**Date of Manufacture:** 10/2010 – 5/2011

**Hazard:** Possible inaccuracy in production resulting in lower waist belt strength of the harness – see a picture



**Till nowadays there are no reports of this defect coming from normal use.** Nonetheless, Singing Rock is acting pro-actively on this matter given the potential casualty hazard.

Based on this matter is decided to change construction of stitching for CRUX and construction change of NARA and NEMO to avoid possible safety hazard.

**PLEASE RETURN THESE HARNESSSES FOR REPLACEMENT WITH A PERFECT PRODUCT.**

**Czech Returns:**

LANEX a.s., division Singing Rock  
Poniklá 317  
512 42 Poniklá

**Other countries returns:**

See-<http://www.singingrock.com/article.asp?nArticleID=1468&nDepartmentID=884&nLanguageID=2>

Thank you for your continued support. Please accept our sincere apologies for any inconvenience this may cause you.